

## **Work Completion Report**





Medi-Clean Solutions | 14/01/2021



### Work Compleation Report

Work Compleation Date				
Senior Site Manager	Drew McGilvray – Managing Director			
Company	Medi-Clean Solutions Limited			
Report Print Date	18/01/2020			
Report Authorised By	Jessica Scriven – Workplace Coordinator			

#### **Contact Information**

Client				
Client Name				
Client Address 1	Onit I Dingley Dusiness Fark			
Client Address 2				
City				
Post Code				

Medi-Clean Solutions | Emergency & Healthcare Cleaning



#### Site Address

Client	
Client Name	
Client Address 1	
Client Address 2	
City	
Post Code	
Report Author	
Medi-Clean Solutions	Drew McGilvray – Managing Director
Client Address	Medi-Clean Solutions
Client Address 2	Unit 4 Gymtech House,
City	Knaresborough
Post Code	нд ојн

Medi-Clean Solutions | Emergency & Healthcare Cleaning



T: 01423 209 013M: 07923 515 983

info@medicleansolutions.co.uk

### System 01-19 – Roof Unit's

System Details			
Name:		- Supply AHU Air Intake Filte Plenum	Pr
Location	Level 4 - Roof		
Location:	All Areas	Usage: General Supply/ Extract	Supply
Decon. Freq	Once Annually		
Last Test Completed	14/01/2021	Work Completion Date:	14/01/2021
Next Test Due	14/01/2022	Next Clean Due:	07/01/2021
AHU's:	19		

### Description

Medi-Clean Solutions were instructed to undertake an overhaul of a stability wite of Solution and the field of the scope of works was to remove all existing AHU filters within the fresh air intake system and replace these for new bag and box filters. The AHU intake was also to be cleaned and maintained in accordance with BESA TR19 & BS-EN:0852 standards. As part of a wider scope of works the intake and AHU internal framework was deep cleaned using medical grade disinfectant to ensure no contamination from the filter changing process or heat recirculation. These units were then documented and all details recorded and compiled in this report.

Medi-Clean Solutions | Emergency & Healthcare Cleaning



M: 07923 515 983

info@medicleansolutions.co.uk

EXCUTIVE SUMMARY		
Total AHU's Cleaned	19	
No. of filters changed	684	
No. of filters removed	684	
Total number of filters installed / removed	1,368	
Total number of coil's cleaned	19	
Percentage of AHU's PASSED compliance on completion	100%	
ADDITIONAL ISSUES		
Number of faults identified	4	
Number of broken or damaged door lock	2	
Number of broken of damaged door hinges	1	
Number of other damaged or broken components	1	
Fault Report		
AHU 2: Damaged door hinge to Intake filter plenum AHU 12: Broken door latch		
AHU 16: Damaged door hinge AHU 17: Heavily corroded VCD within the intake plenum		

Medi-Clean Solutions | Emergency & Healthcare Cleaning



M: 07923 515 983

info@medicleansolutions.co.uk

Location	AHU Number	All filters intact within the Compartment?	Does the system adhere to TR/19 on initial inspection?	Do the filters require changing?	Do the filters require changing on initial inspection?	Were the filters changed on inspection?	AHU cleaned?	Does the area of work comply with TR/19 & BS- EN:0852 on completion?
L4 – Roof	1	Y		Y	Y	Y	Y	Υ
L4 – Roof	2	γ		Y	Υ	Y	Y	Y
L4 – Roof	3	Y		Y	Y	Y	Y	Y
L4 – Roof	4	у	N	у	у	Y	У	у
L4 – Roof	5	Y	Ν	Y	Y	Y	Y	Y
L4 – Roof	6	Y	Ν	Y	Y	Y	Y	Y
L4 – Roof	7	Y	N	Y	Y	Y	Y	Y
L4 – Roof	8	y	N	Y	Y	Y	Y	Y
L4 – Roof	9	N	Ν	Y	у	Y	Y	Y
L4 – Roof	10	Y	Ν	у	Y	Y	Y	Y
L4 – Roof	11	Y	Ν	Y	Y	Y	Y	Y
L4 – Roof	12	N	Ν	Y	Y	Y	Y	Y

Medi-Clean Solutions | Emergency & Healthcare Cleaning



M: 07923 515 983

info@medicleansolutions.co.uk

Location	AHU Number	All filters intact within the Compartment?	Does the system adhere to TR/19 on initial inspection?	Do the filters require changing?	Do the filters require changing on initial inspection?	Were the filters changed on inspection?	AHU cleaned?	Drop Test Successfully Completed and Reset?
L4 – Roof	13	γ		Y	Y	Y	Y	Y
L4 – Roof	14	Y	N	Y	Y	Y	Y	Y
L4 – Roof	15	Y	Ν	Y	Y	Y	Y	Y
L4 – Roof	16	Ν	Ν	у	у	Y	У	У
L4 – Roof	17	Y	Ν	Y	Y	Y	Y	Y
L4 – Roof	18	Y	Ν	Y	Y	Y	Y	Y
L4 - Roof	19	N	Ν	Y	Y	Y	Y	Y

Medi-Clean Solutions | Emergency & Healthcare Cleaning



#### Access Report

COMPLETE ACCESS

Access was gained via the AHU housing using confined space trained operatives while adequately ventilating the work area using VCD manual overrides & propping AHU doors open to ensure throughflow of air and adequate aeration of the work area.

#### Regulations

Our works were undertaken in accordance with the following legislation:

BS-EN:0852 & BESA TR/19 Standards set out the industry benchmark in ventilation hygiene. All works completed are in compliance of these regulations and all works surveyed are done so ensuring that it is the expectation of the client to achieve a minimum standard equal to or greater than the parameters set out within.

British Standard En 15780: 2011 – Ventilation for buildings – ductwork – cleanliness of ventilation systems. ISBN 978 0 580 74008 4

BSRiA Facilities Management Series FMS1/1997 - Guidance to the specification for ventilation hygiene. ISBN 0860224546

**BESA TR/19 Standards 2019** - Section 4 of TR/19 Standards outlines specific considerations for Air Handling Units which are more commonly referred to as "AHU's".

Medi-Clean Solutions | Emergency & Healthcare Cleaning



### Air Handling Unit

Air handling units or AHU's for short, play a vital role in ensuring the temperature and quality of the air we breath within an otherwise confined space within a building. With the multifunction of air supply and extraction as well as filtering and heat regeneration, air handling units control the quality of the air we breath and the temperature of the environment we all work in.

Poor maintenance of air handling units can lead to an increase in staff absence as well as the formation or spread of bacterial or viral infestations, fungus or infections. It is recommended monthly visual inspections are completed to ensure the integrity of the unit. This is to include all system filtration & recirculation. 3-monthly inspection of all mechanical components is recommended to ensure the lifespan of these units and to ensure that adequate filtration installed to suit the environment.

#### Safety Legislation Compliance

Ensuring that all systems remain compliant is key to both client and contractor. Completing regular inspections by approved Naaduk or BESA trained engineers is vital to ensuring all areas of concern are identified, reported and rectified in a timely manner. Medi-Clean Solutions holds all relevant trade body and service association accreditations to ensure they provide the highest level of technical knowledge in the industry alongside providing the highest level of service available.

**Medi-Clean Solutions** | Emergency & Healthcare Cleaning



**Air Handling Unit Maintenance Report** 



M: 07923 515 983

info@medicleansolutions.co.uk

AHU 19 – Supply Intake Plenum	System Risk Level	LOW
L4 - Roof	System Fault Warning	N/A
<section-header></section-header>		<image/>



T: 01423 209 013M: 07923 515 983

info@medicleansolutions.co.uk

AHU 19 – Supply Intake Plenum	System Risk Level	LOW
L4 - Roof	System Fault Warning	N/A
<section-header></section-header>		AFTER



M: 07923 515 983

info@medicleansolutions.co.uk

	AHU 19 – Supply Intake Plenum	System Risk Level	LOW
	L4 - Roof	System Fault Warning	N/A
BEFORE		AFTER	



# AHU Cleaning Certificate

## **Certificate Number**

## 0000 / DC8729-21341 / 02133

This is to certify that the following services have CBRE Client been performed upon the ventilation system listed below **Site Address** AMAZON BRS1 Roof Level 4 AHU: 19 Area: Average pre cleaning miron Cleaned 1,200um Inspected reading Disinfected Tested **Medi-Clean Solutions** Emergency & Healthcare Cleaning





M: 07923 515 983


#### info@medicleansolutions.co.uk

AHU 18 – Supply Intake Plenum	System Risk Level	LOW
L4 - Roof	System Fault Warning	N/A
<section-header></section-header>	AFTER	



M: 07923 515 983


info@medicleansolutions.co.uk





M: 07923 515 983

info@medicleansolutions.co.uk





# AHU Cleaning Certificate

## **Certificate Number**

## 0000 / DC8729-21341 / 02133


This is to certify that the following services have CBRE Client been performed upon the ventilation system listed below **Site Address** AMAZON BRS1 Roof Level 4 AHU: 18 Area: Average pre cleaning miron Cleaned 1,200um Inspected reading Disinfected Tested **Medi-Clean Solutions** Emergency & Healthcare Cleaning





M: 07923 515 983


info@medicleansolutions.co.uk





M: 07923 515 983

info@medicleansolutions.co.uk





M: 07923 515 983

info@medicleansolutions.co.uk

	AHU 17 – Supply Intake Plenum	System Risk Level	LOW
	L4 - Roof	System Fault Warning	N/A
BEFORE		AFTER	



# AHU Cleaning Certificate

## **Certificate Number**

## 0000 / DC8729-21341 / 02133


This is to certify that the following services have CBRE Client been performed upon the ventilation system listed below Site Address AMAZON BRS1 Roof Level 4 AHU: 17 Area: Average pre cleaning miron Cleaned 1,200um Inspected reading Disinfected Tested **Medi-Clean Solutions** Emergency & Healthcare Cleaning





M: 07923 515 983

info@medicleansolutions.co.uk





M: 07923 515 983

info@medicleansolutions.co.uk

AHU 16 – Supply Intake Plenum	System Risk Level	LOW
L4 - Roof	System Fault Warning	N/A
<section-header></section-header>	AFTER	



M: 07923 515 983

info@medicleansolutions.co.uk

	AHU 16 – Supply Intake Plenum	System Risk Level	LOW
	L4 - Roof	System Fault Warning	N/A
BEFORE	<image/>	AFTER	



T: 01423 209 013M: 07923 515 983

info@medicleansolutions.co.uk

## **AHU Cleaning Certificate**

**Certificate Number** 

## 0000 / DC8729-21341 / 02133



Medi-Clean Solutions | Emergency & Healthcare Cleaning



M: 07923 515 983


#### info@medicleansolutions.co.uk

		info@medicleansolutions.co.uk		
	AHU 15 – Supply Intake Plenum L4 - Roof	System Risk Level System Fault Warning	LOW N/A	
BEFORE	<image/>	AFTER		



M: 07923 515 983

info@medicleansolutions.co.uk





M: 07923 515 983

info@medicleansolutions.co.uk

	AHU 15– Supply Intake Plenum L4 - Roof		m Risk Level Fault Warning	LOW N/A
BEFORE		AFTER		



# AHU Cleaning Certificate

## **Certificate Number**

## 0000 / DC8729-21341 / 02133

This is to certify that the following services have CBRE Client been performed upon the ventilation system listed below Site Address AMAZON BRS1 Roof Level 4 AHU: 15 Area: Average pre cleaning miron Cleaned 1,200um Inspected reading Disinfected Tested **Medi-Clean Solutions** Emergency & Healthcare Cleaning





M: 07923 515 983

info@medicleansolutions.co.uk

AHU 14 – Supply Intake Plenum	System Risk Level	LOW
L4 - Roof	System Fault Warning	N/A
<section-header></section-header>	AFTER	



M: 07923 515 983

info@medicleansolutions.co.uk

AHU 14 – Supply Intake Plenum	System Risk Level	LOW
L4 - Roof	System Fault Warning	N/A
	AFTER	



M: 07923 515 983

info@medicleansolutions.co.uk

AHU 14 – Supply Intake Plenum	System Risk Level	LOW
L4 - Roof	System Fault Warning	N/A
<section-header></section-header>	AFTER	



# AHU Cleaning Certificate

## **Certificate Number**

## 0000 / DC8729-21341 / 02133

This is to certify that the following services have CBRE Client been performed upon the ventilation system listed below **Site Address** AMAZON BRS1 Roof Level 4 AHU: 14 Area: Average pre cleaning miron Cleaned 1,200um Inspected reading Disinfected Tested **Medi-Clean Solutions** Emergency & Healthcare Cleaning





M: 07923 515 983

info@medicleansolutions.co.uk

AHU 13 – Supply Intake Plenum	System Risk Level	LOW
L4 - Roof	System Fault Warning	N/A
<section-header><section-header></section-header></section-header>	AFTER	



M: 07923 515 983

info@medicleansolutions.co.uk

	AHU 13 – Supply Intake Plenum	System Risk Level	LOW
	L4 - Roof	System Fault Warning	N/A
BEFORE		AFTER	



M: 07923 515 983

info@medicleansolutions.co.uk

AHU 13 – Supply Intake Plenum	System Risk Level	LOW
L4 - Roof	System Fault Warning	N/A
<section-header><section-header></section-header></section-header>	AFTER	



# AHU Cleaning Certificate

#### **Certificate Number**

## 0000 / DC8729-21341 / 02133

This is to certify that the following services have CBRE Client been performed upon the ventilation system listed below Site Address AMAZON BRS1 Roof Level 4 AHU: 13 Area: Average pre cleaning miron Cleaned 1,200um Inspected reading Disinfected Tested **Medi-Clean Solutions** Emergency & Healthcare Cleaning


Unit 4, Gymtech House, Whincup Avenue, Knaresborough, North Yorkshire HG5 0JH | medicleansolutions.co.uk





M: 07923 515 983


info@medicleansolutions.co.uk





M: 07923 515 983

info@medicleansolutions.co.uk





M: 07923 515 983

info@medicleansolutions.co.uk

AHU 12 – S	upply Intake Plenum L4 - Roof		em Risk Level n Fault Warning	LOW N/A
		AFTER		



# AHU Cleaning Certificate

### **Certificate Number**

## 0000 / DC8729-21341 / 02133

This is to certify that the following services have CBRE Client been performed upon the ventilation system listed below **Site Address** AMAZON BRS1 Roof Level 4 AHU: 12 Area: Average pre cleaning miron Cleaned 1,200um Inspected reading Disinfected Tested **Medi-Clean Solutions** Emergency & Healthcare Cleaning

Unit 4, Gymtech House, Whincup Avenue, Knaresborough, North Yorkshire HG5 0JH | medicleansolutions.co.uk





M: 07923 515 983


#### info@medicleansolutions.co.uk

AHU 11 – Supply Intake Plenum	System Risk Level	LOW
L4 - Roof	System Fault Warning	N/A
<section-header></section-header>	AFTER	



M: 07923 515 983

info@medicleansolutions.co.uk





M: 07923 515 983

info@medicleansolutions.co.uk

	AHU 11 – Supply Intake Plenum L4 - Roof		n Risk Level Fault Warning	LOW N/A
BEFORE		AFTER		



# AHU Cleaning Certificate

### **Certificate Number**

## 0000 / DC8729-21341 / 02133

This is to certify that the following services have CBRE Client been performed upon the ventilation system listed below Site Address AMAZON BRS1 Roof Level 4 AHU: 11 Area: Average pre cleaning miron Cleaned 1,200um Inspected reading Disinfected Tested **Medi-Clean Solutions** Emergency & Healthcare Cleaning

Unit 4, Gymtech House, Whincup Avenue, Knaresborough, North Yorkshire HG5 0JH | medicleansolutions.co.uk





M: 07923 515 983


info@medicleansolutions.co.uk

AHU 10 – Supply Intake Plenum	System Risk Level	LOW
L4 - Roof	System Fault Warning	N/A
<section-header></section-header>	AFTER	



M: 07923 515 983

info@medicleansolutions.co.uk





M: 07923 515 983

info@medicleansolutions.co.uk

AHU 10 – Supply Intake Plenum	System Risk Level	LOW
L4 - Roof	System Fault Warning	N/A
<section-header><section-header></section-header></section-header>	AFTER	



# AHU Cleaning Certificate

### **Certificate Number**

## 0000 / DC8729-21341 / 02133

This is to certify that the following services have CBRE Client been performed upon the ventilation system listed below **Site Address** AMAZON BRS1 Roof Level 4 AHU: 10 Area: Average pre cleaning miron Cleaned 1,200um Inspected reading Disinfected Tested **Medi-Clean Solutions** Emergency & Healthcare Cleaning

Unit 4, Gymtech House, Whincup Avenue, Knaresborough, North Yorkshire HG5 0JH | medicleansolutions.co.uk






M: 07923 515 983

#### info@medicleansolutions.co.uk

AHU 9 – Supply Intake Plenum	System Risk Level	LOW
L4 - Roof	System Fault Warning	N/A
<section-header></section-header>	AFTER	





M: 07923 515 983

info@medicleansolutions.co.uk

AHU 09 – Supply Intake Plenum	System Risk Level	LOW
L4 - Roof	System Fault Warning	N/A
<section-header></section-header>	AFTER	



# AHU Cleaning Certificate

### **Certificate Number**

## 0000 / DC8729-21341 / 02133

This is to certify that the following services have CBRE Client been performed upon the ventilation system listed below Site Address AMAZON BRS1 Roof Level 4 AHU: 9 Area: Average pre cleaning miron Cleaned 1,200um Inspected reading Disinfected Tested **Medi-Clean Solutions** Emergency & Healthcare Cleaning


Unit 4, Gymtech House, Whincup Avenue, Knaresborough, North Yorkshire HG5 0JH | medicleansolutions.co.uk






M: 07923 515 983

info@medicleansolutions.co.uk







M: 07923 515 983

info@medicleansolutions.co.uk

	AHU 8– Supply Intake Plenum	System Risk Level	LOW
	L4 - Roof	System Fault Warning	N/A
BEFORE		AFTER	



# AHU Cleaning Certificate

#### **Certificate Number**

## 0000 / DC8729-21341 / 02133

This is to certify that the following services have CBRE Client been performed upon the ventilation system listed below **Site Address** AMAZON BRS1 Roof Level 4 AHU: 8 Area: Average pre cleaning miron Cleaned 1,200um Inspected reading Disinfected Tested **Medi-Clean Solutions** Emergency & Healthcare Cleaning


Unit 4, Gymtech House, Whincup Avenue, Knaresborough, North Yorkshire HG5 0JH medicleansolutions.co.uk





M: 07923 515 983

info@medicleansolutions.co.uk





M: 07923 515 983

info@medicleansolutions.co.uk

AHU 7 – Supply Intake Plenum	System Risk Level	LOW
L4 - Roof	System Fault Warning	N/A
<section-header><section-header></section-header></section-header>	AFTER	



M: 07923 515 983

info@medicleansolutions.co.uk

AI	HU 7 – Supply Intake Plenum L4 - Roof		tem Risk Level m Fault Warning	LOW N/A
BEFORE	<image/>	AFTER		



# AHU Cleaning Certificate

### **Certificate Number**

## 0000 / DC8729-21341 / 02133

This is to certify that the following services have CBRE Client been performed upon the ventilation system listed below Site Address AMAZON BRS1 Roof Level 4 AHU: 7 Area: Average pre cleaning miron Cleaned 1,200um Inspected reading Disinfected Tested **Medi-Clean Solutions** Emergency & Healthcare Cleaning

Unit 4, Gymtech House, Whincup Avenue, Knaresborough, North Yorkshire HG5 0JH medicleansolutions.co.uk

National Association of Air Duct-



M: 07923 515 983


info@medicleansolutions.co.uk

AHU 6 – Supply Intake Plenum	System Risk Level	LOW
L4 - Roof	System Fault Warning	N/A
<section-header></section-header>	AFTER	



M: 07923 515 983

info@medicleansolutions.co.uk





M: 07923 515 983

info@medicleansolutions.co.uk

	AHU 6 – Supply Intake Plenum	System Risk Level	LOW
	L4 - Roof	System Fault Warning	N/A
BEFORE	<image/>	AFTER	



# AHU Cleaning Certificate


### **Certificate Number**


## 0000 / DC8729-21341 / 02133

This is to certify that the following services have CBRE Client been performed upon the ventilation system listed below **Site Address** AMAZON BRS1 Roof Level 4 AHU: 6 Area: Average pre cleaning miron Cleaned 1,200um Inspected reading Disinfected Tested **Medi-Clean Solutions** Emergency & Healthcare Cleaning

Unit 4, Gymtech House, Whincup Avenue, Knaresborough, North Yorkshire HG5 0JH medicleansolutions.co.uk









M: 07923 515 983

info@medicleansolutions.co.uk

	AHU 5 – Supply Intake Plenum	System Risk Level	LOW
	L4 - Roof	System Fault Warning	N/A
BEFORE		AFTER	



# AHU Cleaning Certificate

### **Certificate Number**

## 0000 / DC8729-21341 / 02133

This is to certify that the following services have CBRE Client been performed upon the ventilation system listed below Site Address AMAZON BRS1 Roof Level 4 AHU: 5 Area: Average pre cleaning miron Cleaned 1,200um Inspected reading Disinfected Tested **Medi-Clean Solutions** Emergency & Healthcare Cleaning

Unit 4, Gymtech House, Whincup Avenue, Knaresborough, North Yorkshire HG5 0JH medicleansolutions.co.uk






M: 07923 515 983

#### info@medicleansolutions.co.uk

AHU 4 – Supply Intake Plenum	System Risk Level	LOW
L4 - Roof	System Fault Warning	N/A
<section-header></section-header>	AFTER	





M: 07923 515 983

info@medicleansolutions.co.uk

AHU 4 – Supply Intake Plenum		System Risk Level	LOW
L4 - Roof		System Fault Warning	N/A
<section-header></section-header>	AFT	TER	



# AHU Cleaning Certificate

### **Certificate Number**

### 0000 / DC8729-21341 / 02133

This is to certify that the following services have CBRE Client been performed upon the ventilation system listed below **Site Address** AMAZON BRS1 Roof Level 4 AHU: 4 Area: Average pre cleaning miron Cleaned 1,200um Inspected reading Disinfected Tested **Medi-Clean Solutions** Emergency & Healthcare Cleaning






M: 07923 515 983

info@medicleansolutions.co.uk


	AHU 3 – Supply Intake Plenum L4 - Roof		vstem Risk Level eem Fault Warning	LOW N/A
BEFORE		AFTER		





M: 07923 515 983

info@medicleansolutions.co.uk





# AHU Cleaning Certificate

### **Certificate Number**

### 0000 / DC8729-21341 / 02133

This is to certify that the following services have CBRE Client been performed upon the ventilation system listed below Site Address AMAZON BRS1 Roof Level 4 AHU: 3 Area: Average pre cleaning miron Cleaned 1,200um Inspected reading Disinfected Tested **Medi-Clean Solutions** Emergency & Healthcare Cleaning


NAAD National Association of Air Duct-Cleaners UK



M: 07923 515 983

#### info@medicleansolutions.co.uk

			integrited	
	AHU 2 – Supply Intake Plenum L4 - Roof		System Risk Level stem Fault Warning	LOW N/A
BEFORE	<image/>	AFTER		





M: 07923 515 983

info@medicleansolutions.co.uk

AHU 2 – Supply Intake Plenum	System Risk Level	LOW
L4 - Roof	System Fault Warning	N/A
<section-header></section-header>	AFTER	



# AHU Cleaning Certificate

### **Certificate Number**

### 0000 / DC8729-21341 / 02133


This is to certify that the following services have CBRE Client been performed upon the ventilation system listed below **Site Address** AMAZON BRS1 Roof Level 4 AHU: 2 Area: Average pre cleaning miron Cleaned 1,200um Inspected reading Disinfected Tested **Medi-Clean Solutions** Emergency & Healthcare Cleaning

National Association of Air Duct-



M: 07923 515 983

info@medicleansolutions.co.uk





M: 07923 515 983


info@medicleansolutions.co.uk

	AHU 1 – Supply Intake Plenum	System Risk Level	LOW
	L4 - Roof	System Fault Warning	N/A
BEFORE		AFTER	



M: 07923 515 983

info@medicleansolutions.co.uk





# AHU Cleaning Certificate

### **Certificate Number**

### 0000 / DC8729-21341 / 02133

This is to certify that the following services have CBRE Client been performed upon the ventilation system listed below **Site Address** AMAZON BRS1 Roof Level 4 AHU: 2 Area: Average pre cleaning miron Cleaned 1,200um Inspected reading Disinfected Tested **Medi-Clean Solutions** Emergency & Healthcare Cleaning

